



FS-1016MFP / FS-1116MFP Product Library

v.3.0 EUR / August 23, 2010

Contents

	Operating System(s):	Version:
(1) Printer Drivers:		
• GDI Driver	Windows 2000, Windows XP, Windows Vista, Windows 7	2.3.25
(2) Scanner Utilities:		
• TWAIN Driver	Windows 2000, Windows XP, Windows Vista, Windows 7	1.10
• QLINK	Windows 2000, Windows XP, Windows Vista, Windows 7	1.10.12
(3) Other Utilities:		
• KMPrint	Windows 2000, Windows XP, Windows Vista, Windows 7	2.0.1
• Quick Setup	Windows 2000, Windows XP*, Windows Vista	2.0.7
• Virtual Link	Windows 2000, Windows XP, Windows Vista, Windows 7	2.0.1

* Supports 32-bit version of Windows XP only.

Known Issues

All

- Issue:** If the scanner is opened during copying or scanning, the current scan job may be canceled.
- Warning:** When upgrading the drivers from the ones included with Product Library v1.3 or older, you need to uninstall the previous driver version before installing the one included on this CD.
- Issue:** During USB installation on Win9x, "USB Connection" does not go away.
Solution: If USB installation does not proceed automatically and the "USB Connection" dialog box remains open, disconnect and reconnect USB cable to regenerate PnP event and installation process.
- Issue:** Upgrading from old version (Version 1.4 or later) of the Product Library results in two drivers being installed.
Solution: Uninstall the old version of both the scanner driver and the printer driver before installing the new version.

Print

- Issue:** In Microsoft PowerPoint, colored text may be printed as black.
Solution: Change the "Color/Grayscale" setting in PowerPoint from "Grayscale" to "Color".
- Issue:** In Microsoft Word, border lines may be printed in a different style than specified.
- Issue:** In Microsoft Excel, when you print a line chart, the foreground color may not be printed.
- Issue:** When printing PDF files from Adobe Acrobat Reader using reduce or enlarge scaling settings, they may not be applied properly.
Solution: Adjust the "Page Scaling" setting of Acrobat Reader.

Scan

- Issue:** When using the "Copy Function", it may not work properly.
Solution: Change the printer name to "Kyocera FS-1016MFP / FS-1116MFP".
- Issue:** In Acrobat 6.0, scanning using the minimum area setting may not work properly.
- Issue:** When scanning a black and white image, it may be scanned smaller in width.
- Issue:** If the scanner driver was installed through a network connection using Virtual Link, the installer may not be able to upgrade the scanner driver.
Solution: To upgrade scanner driver, use the USB connection; or uninstall and reinstall the scanner driver and the printer driver.
- Issue:** When scanning something smaller than A4/letter size, the preview image may not show correctly.
- Issue:** During upgrading of the Scanner driver, QLink pops up and remains open.
Solution: Close it manually.
- Issue:** The gamma curve value of TWAIN may not be correct.
Solution: Click the Reset button.

Quick Setup

- (1) **Warning:** Temporarily disable any security software and the standard firewall built into the operating system (for Windows XP/7), if applicable.