



Release Notes
Kyocera Product Library CD
for KM-3050/4050/5050
Version 1.1 EUR
August 10th, 2006

Contents of this CD-ROM

- (1) Kyocera KM-3050/4050/5050 Product Library
- (2) Kyocera Printer Driver and FAX and Scanner Utilities
 - (a) KX Printer Driver, v.4.1.1814
 - (b) TWAIN Source, v.1.3.1819
 - (c) Fax Driver v.3.0.1813
- (3) USB Device Drivers and Language Monitors
 - (a) USB Device Driver for Windows 98 & Me, NT4, 2000 and XP v.0.3.1.2
 - (b) Language Monitor for Windows NT 4 v.0.3.259.6, for 9X & Me, v.0.3.258.3
- (4) Printer Utilities
 - (a) KM-NET Viewer, v.4.0.1819
 - (b) KM-NET for Direct Printing, v.2.0.1819
 - (c) KM-NET for Clients, v.3.0.1819
- (5) Network Utility
 - (a) KPrint, v.5.1.6
 - (b) Quick Setup, v.2.0.7
 - (c) Kyocera Printer Deleter, v.2.9.0313
- (6) Macintosh Software
 - (a) Mac OS 9 Driver v.1.0
 - (b) Mac OS 9 Font Installer
 - (c) Mac OS X 10.2 & 10.3 Driver v.1.0
 - (d) Mac OS X 10.2 & 10.3 Font Installer
 - (e) Mac OS X 10.4 Driver v.1.0
 - (f) Mac OS X 10.4 Font Installer
- (7) Documentation
 - (a) KM-NET for Clients – Operation Guide (Engl.)
 - (b) Kyocera Command Center – Operation Guide (Engl.)
 - (c) PRESCRIBE Commands – Command Reference
 - (d) KM-NET for Direct Printing – Operation Guide (Engl.)
 - (e) KX Driver Version 4.1 – User Guide (Engl.)
 - (f) Network FAX Driver – Operation Guide (Engl.)
 - (g) PRESCRIBE Commands – Technical Reference (Engl.)
 - (h) KM-3050, KM-4050, KM-5050 Operation Guide – English, French, German, Italian, Dutch, Spanish, Greek, Polish, Russian, Turkish
 - (i) KM-3050, KM-4050, KM-5050 Advanced Operation Guide & Fax Manual – English, French, German, Italian, Spanish

Known Issues

- (1) **Issue:** When sharing a 32-bit PCL Mini-driver to a Windows 2000 client from a 64-bit server running Windows Server 2003. When an attempt to display Printer Properties or Printing Preferences... on the Windows 2000 client is made, the error messages "Printer Properties cannot be displayed" or "Printer preferences cannot be displayed" are displayed. **Microsoft has acknowledged this is a known issue with the 64-bit version of Windows Server 2003.**
Work Around: Make sure there is a 32-bit Windows XP Client connected to the same server. Install the shared printer on the Windows XP client and set the Printer Properties and Printing Preferences from the Windows XP Client.